Automation Ver 25.0.2.84 Changes and Improvements

Version 25.0.2

SOD-2447 CableList can be mssing information in from/to

SOD-2442 List setup: Selecting criteria on symbol data fields that also are database fields didn't work properly

SOD-2440 Drag'n'drop of subdrawing sometimes doesn't show layer option dialog

SOD-2436 "Next" and "Previous" symbol does not work correctly

SOD-2435 "Update from Componentdatabase" reported error, if generated symbols was used

SOD-2434 Componentmenu incorrectly shows userdefined symbols

SOD-2433 "Save as" in symboledit, does not update title in Automation

SOD-2430 PLC's with "empty" symbols used are reported as an error.

SOD-2429 Change og articlenumber. does not update database-symboldatafields in all symbols

SOD-2428 Drag and drop could make Automation crash

SOD-2427 New function: Possible to remove not placed accessory, when right-clicking in Available accessory column

SOD-2424 Using own article number having the same value as other article numbers for a component, does not work properly

SOD-2421 Components downloaded from the portal don't handle unicode in symbol files

SOD-2408 Panelrouter output doesn't load BuiltInDepth value from database

SOD-2394 update accessories' types

SOD-2390 Check for type-values from database, does access wirenumbers

SOD-2382 Change of visibility on multiple symbols' type texts, changes type text contents

SOD-2347 Linedata: Router did place texts wrong

SOD-2286 Auto PLCplacement can leave blanks

SOD-2221 Missing US texts in "Generate project with selected options"

AUTO-8222 PLC ref symbols are considered 'Not correct symbols' when running 'Update from Component database'

AUTO-8219 Some PLCs are not shown on mechanical pages

AUTO-8191 Czech, Chinese and Swedish texts were not present when downloading from portal.

AUTO-8182 [Improvement] EMPTY symbols in plc reference symbols must also have article numbers

Version 25.0.1

SOD-2409 V22 database conversion: Mapping of field 'UnitForUPP' was not possible

SOD-2401 Copy of page with PLC's takes a long time

SOD-2399 Green dot showing accessory is outside the selection box from now

SOD-2398 Objectlists (F7) could make Automation crash with older operating systems

SOD-2397 The componentwizard could be setup to access same fields multiple times

SOD-2396 The Project generator deleted information of paths, if path names contained spaces

SOD-2395 When a sub-drawing was placed, not only were the symbol data fields on that sub-drawing updated, but the entire page was also updated

SOD-2357 Placing a subdrawing may in rare cases lead to changed article numbers in the project

AUTO-8176 "Component Search"-dialog was casesensitive

AUTO-8159 Wrong data on placed subdrawing, if inserted multiple times

AUTO-8153 Accessory could increase, when Component grouping (Ctrl+F7)

AUTO-8077 Multilists to exportfile