

Automation Ver 24.0.2.70 Changes and Improvements

Version 24.0.2

SOD-2346 Multiple symbols on same group number dont show as an error
SOD-2345 "Next free" in componentdialog, only works when using default RDS-setup
SOD-2344 Wrong symbolstate when placing subdrawing
SOD-2341 Component article changes even if cancel is clicked.
SOD-2340 Components don't get updated when changing articlenumber
SOD-2339 Project conversion (v22-24): Incorrect article numbers were listed in some cases when subdrawing models were used
SOD-2337 Symbol placed, can't be deleted again.
SOD-2336 Remap function could not handle some cases
SOD-2335 Crash, when using undo
SOD-2334 Crash in ComponentWizard, when opened and closed.
SOD-2333 Mounting assist crashes when updating labels
SOD-2332 Crash when clicking select direction for symbol
SOD-2331 When selecting RDS, not all text is shown i combobox
SOD-2330 Component Wizard, don't detect cables from comp.portal as cables.
SOD-2328 Componentwizard could find libtype declared in project, instead of direct from the actual symbol.
SOD-2327 Import V22-database gives error (in Norwegian language)
SOD-2323 Textplacement in Design symbol did overlap
SOD-2322 Componentmenu could crash on close
SOD-2320 Import of usersettings don't process all groups.
SOD-2319 Symbol names updated when deleting, copying, cutting pages.
SOD-2318 Load of project, and update list should not ask for picture resize
SOD-2317 Some not-desired side effects of the plc ref grouping function have been fixed
SOD-2306 Select RDS in rename dialog is very slow
SOD-2215 The number of decimals/precision on floating point numbers in lists and in the database grid did not match
SOD-1838 Import DWG/DXF: Missing lines
SOD-1618 Autonumbering of pins across symbols.
AUTO-8074 Componentmenu did not show errors when component has mixed articlenumbers
AUTO-8073 Symbols for component dont show all symbols
AUTO-8061 Mounting assistant could crash, because of disk or networkproblems.
AUTO-8059 Crash when opening projects internal database
AUTO-8058 When opening a V22 (or lower) project, the componentmenu might show "white" boxes.
AUTO-8057 Usersettings are not loaded correctly in Import V22 database
AUTO-8056 [Improvement] V22-24 db import: If a PCSSET file is used it is no longer necessary to point out an IDB file
AUTO-8055 [Improvement] Import of database, sets a default filter that exclude obsolete
AUTO-8053 [Improvement] Import from database does not give a detailed list of missing articles
AUTO-8052 [Improvement] Updating components from portal, should give settings before runned.
AUTO-8042 Update of components from portal, now also updates/imports components from the active project if missing
AUTO-8041 Sometimes the program shows wrong usr/pcs status for placed components (Mec.load)
AUTO-8036 CW: ved rediger/kopier bliver kun pcsDIA-, pindata og MEC-symboler kopieret
AUTO-8033 Wrong priority of article numbers are selected for lists etc, when ManufacturersArtNo starts with UNKNOWN
AUTO-8029 [Improvement] Copy of page with PLC can take a long time
AUTO-8017 In "Design symbol", datafields with "activate next", now has a green marker
AUTO-8016 When saving a symbol, list-datafields will align by y-values.
AUTO-8015 When saving in "Design symbol", check that everything is inside drawing area
AUTO-8011 Problem with right selection of alternatives when IO symbol is placed first
AUTO-8010 Errors when multi placing terminals with jumper connections
AUTO-8009 [Improvement] Option in Special settings: Default fokus on OK or All can be set by the user

Version 24.0.1

SOD-2303 All options are not visible when running textsize higher than 100%
SOD-2302 When you import a ver22 file, you will only be asked to map unknown database data fields
SOD-2297 Information dialog. Size did not adapt to text.
SOD-2296 Message dialog, text was cut off
SOD-2295 Datafields on symbol does not always show in symboleditor
SOD-2294 Issues with subdrawings and portal/user status on symbols
SOD-2292 Project could not be loaded
SOD-2290 Automatic page numbering did work in some cases
SOD-2289 It is not possible to insert objects in the Pickmenus
SOD-2288 Pagenumbers when using the Project Generator might be wrong
SOD-2282 Mounting Assistant: Selecting an unused RDS-code for filtering creates crash
SOD-2279 It is not possible to Search (ctrl+F) for Wirenumbers that contain a /
SOD-2276 Settings/Text defaults/"Transfer all text settings to the project": Text format for reference frames were set to something incorrect in some cases
SOD-2272 Crash in rare cases in rename dialog/reference designations
SOD-2261 Possibility for full resolution in "Insert picture"
SOD-2243 Renaming of IO-adresses should not be possible if statustypes are different
SOD-2236 Fixed crash in component accessories grid
SOD-2226 Wire numbers were not automatically numbered when a custom RDS format was used
SOD-2184 PLC-IN4 symbol, missing IO statustype

SOD-2167 Lines placed in correct layers in dwg export

SOD-2095 Component list: "List only one of each name" does'nt work if you sort on Symbol data fields.

AUTO-8006 TYPE text on a symbol is now set, when a symbol is placed in a project from outside the project, for instance from a sub-drawing

AUTO-8005 Panelrouter output can make wrong interpretations of mounting direction of wires

AUTO-8004 [Improvement] Connection details in database are now the same as in the program

AUTO-8002 [Improvement] Panelbuilder: Warning in projects with more than one panel

AUTO-8001 [Improvement] Panelbuilder: Indication if Rated Current is above limits

AUTO-7999 Current/page numbering of symbols were incorrect. In some cases, due to incorrect page numbering

AUTO-7998 [Improvement] Panelrouter: New export option - to Phoenix Contacts Wirepicker

AUTO-7997 Project could not be loaded

AUTO-7802 Dialogs associated with the Project Generator do not remember screen and position

AUTO-7140 [Improvement] Exclusion of concatenation sign (<) was not displayed in some cases