

## **Automation Ver 25.0.1.23 Changes and Improvements**

### **Version 25.0.1**

SOD-2409 V22 database conversion: Mapping of field 'UnitForUPP' was not possible

SOD-2401 Copy of page with PLC's takes a long time

SOD-2399 Green dot showing accessory is outside the selection box from now

SOD-2398 Objectlists could make Automation crash older operating systems

SOD-2397 The componentwizard could be setup to access same fields multiple times

SOD-2396 Projectgenerator delete pathinformation, if paths contains spaces

SOD-2395 When a sub-drawing was placed, not only were the symbol data fields on that sub-drawing updated, but the entire page was also updated

SOD-2357 Placing a subdrawing may in rare cases lead to changed article numbers in the project

AUTO-8176 "Component Search"-dialog was casesensitive

AUTO-8159 Wrong data on placed subdrawing, if inserted multiple times

AUTO-8153 Accessory could add one, when using componentgroup

AUTO-8077 Multilists to exportfile