Automation Ver 23.0.2.4 Changes and Improvements

Version 23.0.2

SOD-1953 F4 could course a program crash

SOD-1952 Textfonts like osifont was sometime substituted in pdf export and printing

SOD-1951 Database data fields on cable/terminal/PLC/Net lists is not converted/translated while loading in V23

SOD-1949 Creating a new manufacturer did not always work

SOD-1948 connect Show available PLC to the available address on the reference card using the button I/O addr. could lead to a crash

SOD-1947 Viewer could not open old projects

Version 23.0.1

SOD-1946 Component dialog, accessories, shows correct article number

SOD-1945 'Default to UK' fumction for ie missing manuals on selected language is now working again

SOD-1943 The selection of Article database field was not saved with the project and not in the ini-file

SOD-1942 Selecting PLC I/O Data (right-click) on a PLCreference card (new methode) did not work

SOD-1941 Wrong readressing of PLC reference cards when more than 8 in- or outputs SOD-1938 2 PLCreference cards, e.g. -K1.1 and -K1.2 did not get correct group names

SOD-1937 'All' Text/Symbol defaults are not transferred correctly with the Project Generator. SOD-1936 The Symbol Settings dialog in Symbol Editor is now resizable

SOD-1935 The chosen articlenumver (type) are not always shown when placing a component

SOD-1932 Export dialog size problem on dual monitor with different scale (dpi settings)

SOD-1931 The show available window was not updated when changing Adresses on the PLC-reference symbol

SOD-1928 Layout of datavalues in "Edit record"-dialog, should be improved for number-types.

SOD-1927 Transfer PLC data from Reference symbol failed if reference symbol has no RDS and the I/O symbol has RDS

SOD-1925 Rare crash when 'Show Component' is active

SOD-1924 Crash when dragging from portal, if symbol directory or alias does not exist

SOD-1923 Crash when picking symbol from componentmenu

SOD-1922 Connecting to a database that is not valid for V23, can give crashes

SOD-1921 Crash when selecting component followed by changing the reference designation

SOD-1920 "Change path"-button in URL-links, don't work as expected

SOD-1918 Syncronization between a PLC referensymbol(group) failed

SOD-1917 Database program: When selecting another menu table, the program is searching for an old field name

SOD-1916 Crash when showing hint on accessoryfields in the edit recorddialog.

SOD-1915 Import from v22 database: Attempting to create new custom field failed, if the connected v23 database required user/password

SOD-1914 V22-db-import: Field mappings not always correct, when the user does not use an IDB file

SOD-1913 V22-db-import: Crash if IDB file was used that pointed to a field that did not exist in the table

SOD-1911 Some minnor text display issues in project settings page

SOD-1910 Db22-importer: Crash if user attempts to open text file that does not exist (article number text file)

SOD-1909 Fixed crash in component wizard when changing symbol state in alternative symbol, and when rearranging symbols.

SOD-1908 Part -/Component list: Choose "=+-design." in "Setup/Criteria" press on = sign on the keyboard (crash)

SOD-1906 Terminal list to file: the data field "Cmp. group No." is missing

SOD-1905 In some cases a "Invalid typecast error" was reported when multiple components were imported

SOD-1904 V22-db-import: Import of custom fields did not succeed if the field type was not string

SOD-1901 2 texts in the Mounting assistance function was only English

SOD-1900 A PLCreference group does not ask for a name when placing

SOD-1899 Crash when opening a v22 project if an alternative article number was used (mapped) in the internal project database

SOD-1896 Mixed Portal and user components did not work when using Mechanical placement

SOD-1893 Showing License data in setting or click on Component portal button might raise EConvert Error

SOD-1891 If there is alternatives on PLC then "Place all" does not work on I/O

SOD-1889 'Mechanical load' can only place usr-symbols

SOD-1888 Import from v22 database: File filter for ACCDB was missing in the import dialog

SOD-1885 Import of v22 components: v22 DESCRIPT must be imported into both DescriptUK and DescriptUS

SOD-1884 Edit symbol could sometimes create two Save icons in the toolsbar

SOD-1881 PLC-ref symbols: the (new) symbol groups cannot have current path names or page's rds. This is now fixed

SOD-1878 Edited a symbol, from the symbolmenu can take a long time updating symbol-graphic.

SOD-1876 Placing PLC-referencesymbols by "place all", can't handle componentname correctly

AUTO-7832 Osifont replaces the Albertus Medium font

AUTO-7818 Templates and Frames for A0-A3 for house installations have been created AUTO-7801 Lists to file in the Tools menu did not work

AUTO-7785 If no symbols were found in the area the empty dialog looked odd. The Dialog title has now been changed

AUTO-7771 The functionality in "Show terminal row" now works for all terminals